

VVG-CBN33 行車記錄器

韌體更新方法


1. 請至 VACRON 官網，下載最新的韌體更新檔

<http://www.vacron.com.tw/support1.html>

產品型號	驅動下載	播放軟體下載
WG-CBN33	V2122	PLAYER V2.1.6.74
VVA-CBN01 / VVA-CBN02	-	PLAYER V1.0.0.60
VVA-CBE05A	-	PLAYER V1.0.0.60
VVA-CBE02A	-	PLAYER V1.0.0.61
WH-CBN03	-	PLAYER V2.0.6.19
WG-CBE15	V1200	PLAYER V2.0.6.42
WG-CBN13G	-	PLAYER V2.0.6.60
WG-CBN12	V1200	PLAYER V2.0.6.37
VVA-CBE25	-	PLAYER V1.0.0.56
CDR-E02	-	PLAYER V1.0.0.61
CDR-E05	-	PLAYER V1.0.0.60
CDR-E26	V1079	PLAYER V2.0.5.8
CDR-E26A	V1079	PLAYER V2.0.5.8
CDR-E28	V1079	PLAYER V2.0.5.8
CDR-E07	-	PLAYER V1.0.8.4
CDR-E07(VGA+VGA)	V2010	PLAYER V2.0.6.7
CDR-E07(720P+VGA)	V2023	PLAYER V2.0.6.18
CDR-E22 / CDR-E23	-	PLAYER V1.0.0.60

2. 先將 SD 卡執行格式化 (如有重要檔案請先備份)

3. 將「主機韌體更新檔」解壓縮後，請將更新檔複製至 SD 卡



4. 行車紀錄器於送電前先插入 SD 卡,送電,開機後會出現 UPDATE 更新圖示,即表示進入韌體更新模式·更新完成後會自動重開機(更新過程中請勿將電源斷電,以免造成更新失敗)



5. 更新完成後會進入錄影畫面



更新前請先將記憶卡完全格式化，再放入更新檔案於記憶卡內更新